
FIG. 1



OBLON, SPIVAK, ET AL DOCKET #: 245671US90 INV: Hisaya SUZUKI, et al. SHEET 2 OF 30

FIG. 2




FIG. 3




FIG. 4





FIG. 5






FIG. 7






FIG. 8



OBLON, SPIVAK, ET AL DOCKET #: 245671US90 INV: Hisaya SUZUKI, et al. SHEET <u>8</u> OF <u>30</u>

FIG. 9



## FIG. 10




FIG. 11




FIG. 12





FIG. 13






FIG. 15




FIG. 16




FIG. 18





FIG. 19






FIG. 21





FIG. 22






FIG. 24




FIG. 25




FIG. 26




FIG. 27




FIG. 28






FIG. 29A




P (Pillar)
120 (Light Emitting Unit)
Reflecting Mirror)
S (Automobile Body)
112
(Mirror Housing)
SW (Side Window)

## FIG. 30



## FIG. 31



## FIG. 32




FIG. 33

